Inspection Report

Provided by:



Zee Home Inspection

Inspector: Kashif Muhammad

http//:zeehomeinspection.com

Email: info@zeehomeinspection.com

Ph: 929-301-9902

NJ License # 24G100216700 VA License # 3380002012

Property Address XYZ St Somewhere, NJ 00000



Table Of Contents:

Section name:

Page number:

	. agee
Report Information	
Report Summary Page	6
Grounds	
Exterior	10
Roofing	
Heating - Air	
Electrical	25

 Plumbing
 27

 Interiors
 29

 Kitchen
 34

 Bath All.
 38

 Basement
 40

 Garage - Laundry
 43

 Foundation - Crawl Space
 47

Report Information

Client Information

Client Name John XYZ

Property Information

Approximate Year Built 2001

Approximate Square Footage 2593 sqft

Number of Bedroom 4.

Number of Bath 3.

Direction House Faces North.

Inspection Information

Inspection Date 10/13/2023

Inspection Time 03:00 PM

Weather Conditions Dry.

Outside Temperature 64 °F

Disclaimer

EXCLUSIONS AND LIMITATIONS OF THIS INSPECTION REPORT

- 1. This report shall be confined to those matters specifically stated herein and shall not include any external documents or statements, oral or implied, not explicitly set forth in the written report.
- 2. This report is rendered as a professional opinion based on physical conditions observed by the inspector, his experience, and technical knowledge. It is not intended to be factually or technically and shall assume no responsibility for the cost of replacing any unreported defects of conditions, or for any consequences stemming from any conditions reported or unreported.
- 3. Latent defects are beyond the scope of this report and are specifically excluded. Also excluded are items and conditions that are concealed, inaccessible, camouflaged, or otherwise not easily observed. Swimming pools, tennis courts, playground equipment, and other recreational or leisure time items are excluded along with cosmetic conditions such as, but not limited to; wallpaper and interior painting. Also excluded are complex machinery and hardware requiring specialized technical expertise to assess or repair. Detached structures, other than garages are also excluded from the scope of this report.
- 4. This report is based exclusively on the inspector's observation of conditions at the site as they existed at the time of the inspection only.

- 5. This report and the inspection on which it's based, shall not be constructed to be compliance inspection of any governmental or non-governmental codes, rules, or regulations. 'No opinion is provided as to the legality of any building, improvement, addition, alteration, or of any equipment, whether or not attached to the real property.
- 6. This report and the inspection on which it's based, shall not be intended as a guarantee or warranty, expressed or implied. No implied warranty of merchantability or fitness for a particular purpose or use in stated or intended, regarding the real property itself or the mechanical systems and other items inspected, and this report shall not be intended for such purpose.
- 7. Zee Home Inspection LLC, Its officers, directors, agents, and/ or employees, shall not be held liable for any mistakes, omissions, or errors in judgment and assume no liability or responsibility for any mistakes, omissions, or errors caused by fraud, deception, concealment or camouflage perpetrated by others. It is understood that the liability of Zee Home Inspection LLC., its officers, directors, agents, and/or employees is strictly limited to the cost of the report itself, regardless of the consequential damages of any kind, including but not limited to personal injury and property damage of any nature.
- 8. This report shall not be intended to establish the value of the subject premise or any portion thereof. No representation or recommendation is made or intended regarding the advisability of purchase.

B. NOTICE

- 1. Zee Home Inspection LLC. Attests that the components and elements of the home have been inspected and rated with a "Professional Opinion Only". This report means that Zee has performed an inspection of the home and its components and elements excluding any latent and/ or concealed defects that are not readily accessible and/ or otherwise visible and which could not be identified and/or rated without opening the walls, ceilings and/ or floors, removal of insulation, disassembly of machinery, plumbing, electrical and/or heating system.
- 2. Because some utilities may not have been in service, or climatic or other conditions may not have required maximum output, the adequacy or capacity of heating, cooling, plumbing, and/ or electrical systems could not be determined
- 3 Mechanical and/or electrical systems can fail at any time, often with little or no advanced warning. Accordingly, this report shall reflect the condition of such systems only at the time of the inspection and shall not be considered a guarantee or warranty as to the future operation of said system.

- 4. Zee Home Inspection LLC. I wish to emphasize that the house has been inspected according to the standards of the trade. Zee Home Inspection LLC. However, wished to emphasize that this house is at least 22 years old. This means that many if not all systems are used and worn. Even though, At the time of the inspection, they have been deemed satisfactory and/or acceptable; it shall not mean that before the closing of title, or shortly thereafter, the said system may reach the end of their economic life and as such may require replacement.
- 5. The condition of the premises may change after the date of our inspection due to many factors such as; weather conditions, fire, moisture, leaks, or action(s) of the premises and/ or systems within the scope of the inspection report at the time of the inspection only.
- 6. Zee Home Inspection LLC. Would like to point out the inspection shall not consist of dismantling certain systems or tearing walls apart, digging up basements, pipes, or any action deemed, outside the scope of this report, Rather, this report is done keeping cost factors in mind. Should we deem that specialized services from someone such as a licensed plumber, electrician, roofer, and/or any other specialized professional(s) should be contracted by the buyer, Zee Home Inspection LLC? Will make note of that in the report and that not shall serve as a warning that the item(s) indicated require the attention of a said professional for further, more detailed review.
- 7. The presence of asbestos in the ceiling, insulation, flooring, and/ or pipe covering cannot be determined without laboratory testing in an approved E.P.A.-certified laboratory. Consequently, Zee Home Inspection LLC. Shall not render any opinion as to the nature of said material(s). Independent laboratory analysis is recommended if a question exists as to the composition of any substance(s).

Report Summary Page

This is only a summary of the inspection report and is not a complete list of discrepancies.

- 1. Some back door patio tiles were sinking. Monitor and repair as needed.
- 2. The front door outlet has No power detected during the test. Fix.
- 3. A smoke detector was missing or removed at the lower level. Recommend smoke detectors on each level and near or in each bedroom.
- 4. Both Garage door automatic openers were not operational or disconnected. Repair, replacement, and/or adjustments are needed.
- 5. The upper-level room ceiling register grill was hanging, Repair or secure them for safety reasons.

HOMEBUYERS TAKE NOTICE, ANY ITEM THAT IS LISTED IN THE SUMMARY SHOULD CAUSE REASON FOR CONCERN. IT IS RECOMMENDED THAT A PROFESSIONAL CONTRACTOR, PLUMBER, ELECTRICIAN, ROOFER, ETC. SHOULD BE CONTACTED REGARDING THESE ITEMS FOR FURTHER INVESTIGATION AND OR REPAIR/REPLACEMENT.

Grounds

1.5 Patio Deck Conditions (Repair)

- Some back door patio tiles were sinking noticed at the inspection time. Water erosion is one of the most common reasons for a patio to sink or dip over time.
- This soil can be affected by water erosion causing a dip in your patio. Recommend A "Licensed Contractor" is suggested to be contacted for further evaluation and repair or to obtain examination and analysis by a qualified professional, tradesman, or service technician.

Exterior

2.8 Outlet Conditions (Repair)

• The front door outlet appeared to be in serviceable condition at the time of the inspection. No power was detected during the test. A "Licensed Electrical Contractor" is suggested to be contacted for further evaluation and repair or to obtain examination and analysis by a qualified professional, tradesman, or service technician.

Heating - Air

4.2 Distribution Conditions (Safety)

• The upper-level room ceiling register grill was hanging, Repair or secure them for safety reasons.

Interiors

7.10 Smoke Detector Conditions (Safety)

• A smoke detector was missing or removed at the lower level. Recommend smoke detectors on each level and near or in each bedroom. The client should contact the local Fire Marshall's office for proper locations.

1 Grounds

Grading

Grading Slope

The site is moderately sloped.

1.1) Grading Conditions

Inspected.









Driveways - Sidewalks - Walkways

Driveway Material

Concrete.

1.2) Driveway Conditions

• Inspected and no Major deficiencies were noted at the time of the inspection.



Driveway ok.

Sidewalk Material

Concrete Pavers.

1.3) Sidewalk Conditions

Inspected.



Frontwalk ok.



Sidewalk ok.

Retaining Wall

Retaining Wall Material

Block.

1.4) Retaining Wall Conditions

Inspected.

Patio Deck

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected

Style Concrete patio

1.5) Patio Deck Conditions



- Some back door patio tiles were sinking noticed at the inspection time. Water erosion is one of the most common reasons for a patio to sink or dip over time.
- This soil can be affected by water erosion causing a dip in your patio. Recommend A "Licensed Contractor" is suggested to be contacted for further evaluation and repair or to obtain examination and analysis by a qualified professional, tradesman, or service technician.







Sinking tiles.

2 Exterior

Front - Back Entrance

Front Entrance Type

Front Door.

2.1) Front Entrance Conditions

• Inspected and no Major deficiencies were noted at the time of the inspection.



Front door ok.

Back Entrance Type

Multiple back doors.

2.2) Back Entrance Conditions



Sliding door ok,.

Exterior Walls

Structure Type Wood frame.

Exterior Wall Covering

The visible and accessible areas of the exterior siding material are vinyl.

2.3) Exterior Wall Conditions

Inspected.

Exterior Windows - Doors

Window Type Double Hung.

Window Material Wood.

2.4) Window Conditions



Exterior windows ok,







Bay window ok,.

2.5) Exterior Door Conditions

Inspected.

Exterior Water Faucet(s)


Faucet Location

• North & south side of the house.

2.6) Faucet Conditions

• Tested and in working condition on the day of inspection.







Exterior back Faucet FYI only,.

Chimney


2.7) Chimney Conditions



• Inspected and no Major deficiencies were noted at the time of the inspection. Recommend getting your chimney cleaned and inspected once a year by a qualified professional.



wooden fire chimney ok.



Flashings ok.



Fre-bab chimney ok.



AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected





Chimney cap ok.

Exterior outlets.

Outlet GFCI

Outside outlets were present at the time of the inspection.

2.8) Outlet Conditions



• The front door outlet appeared to be in serviceable condition at the time of the inspection. No power was detected during the test. A "Licensed Electrical Contractor" is suggested to be contacted for further evaluation and repair or to obtain examination and analysis by a qualified professional, tradesman, or service technician.



Front door Outlet.

3 Roofing

Roof Covering

Method of Inspection

The roof was inspected by high high-efficiency drone.

Roof Style

Roof Covering Material

Number of Layers

Combination of gable and hip.

Asphalt composition shingles.

One.

3.1) Roof Covering Condition

• Inspected and no Major deficiencies were noted at the time of the inspection.

































3.2) Flashing Conditions

Inspected.

3.3) Gutter & Downspout Conditions

Inspected.

3.4) Window Wells.

Inspected.

Attic Area

Attic Access

• The attic access was located at the upper level.



Pull down attic FYI only.

Method of Inspection

Entered attic area.

Roof Frame Type

The roof framing is constructed with rafter framing.

3.5) Attic Conditions

• Inspected and no Major deficiencies were noted at the time of the inspection.



Attic





Sheathing ok .








Attic Ventilation Type

Gable Vents.Soffit vents.

3.6) Attic Ventilation Conditions

Inspected.



Example.

Attic Insulation Type

Batt Insulation.

3.7) Attic Insulation Conditions

• The attic has fiberglass batt insulation. The approximate depth of the insulation is 8 to 10 inches. This appears adequate. I.



Insulation ok.



Insulation ok.

4 Heating - Air

Heating

Location of Unit 2 Heat units were noted, one in the attic and 2nd was in

the basement.

Heating Type Forced Air.

Energy Source Natural Gas.

Approximate BTU Rating The BTU's were not available.

4.1) Unit Conditions

1. The upper-level unit Tempstar heat pump was built or installed between **the years 1999 to 2002 aged likely**. Tested and in working condition on the day of inspection.

- 2. The lower level heat pump was Tempstar heat pump was built or installed between **the years 1999 to 2002 aged likely.** Tested and in working condition on the day of inspection.
- Proper and regular heat pump maintenance is crucial for a long-term and economical heating and cooling operation. If the unit is not cleaned and maintained per instructions and manual, it might deteriorate over time, lose efficiency and performance, or simply malfunction.
- The average life expectancy of a heat pump is 10 to 15 years. Most manufacturers guarantee at least 15 years of reliable use, while a few go up to 25 years. However, rarely will you find a manufacturer promising more than thirty years. On the other end of the scale, many heat pumps will give you at least ten years of reliable use.




Lower level HVAC



Data plate.



Attic Unit.



Maintenance data.

Distribution Type

• The visible areas of the heat distribution system are ductwork with registers.

4.2) Distribution Conditions



• The upper-level room ceiling register grill was hanging, Repair or secure them for safety reasons.





4.3) Ventilation Conditions

Inspected.

4.4) Thermostat Location and condition.

• Tested and in working condition on the day of inspection.

Air Condition - Cooling

Type of Cooling System

Air Cooled Central Air Conditioning

Heat temp ok.


AC Unit Power 208/240 volts

4.5) AC Unit Conditions

• Tested and in working condition on the day of inspection.



A/C units



2nd unit A/C unit.



Data plate.



Data plate.

5 Electrical

Service Drop - Weatherhead

Electrical Service Type

The electrical service is underground.

Electrical Service Material

Copper.

Number of Conductors

Two.

5.1) Electrical Service Conditions

Inspected.



Electric Meter ok.

Main Electrical Panel

Main Disconnect Location

At Main Panel.

Electric Panel Location

• The main electric panel is located in the garage.

Panel Amperage Rating

 The electrical capacity of the main breaker was listed as 120/240 labeled as 200 amps.

Circuit Protection Type


Breakers.

5.2) Wiring Methods

The main power cable is copper. The branch cables are copper.

5.3) Electrical Panel Conditions





Main Electric Panel.



Main Electric disconnect. FYI only.



Electrical Subpanel

Subpanel Location

5.4) Subpanel Conditions

N/A, Not present or was not visible at the time of the inspection.

N/A

6 Plumbing

Water Main Line

Main Shutoff Location


Main Line Material

The main valve is located in the basement.


The visible material of the main line/pipe appears to be copper.

6.1) Main Line & Valve Conditions

Inspected.



Water meter.



Main water shut off valve. FYI only,.

Water Supply Lines

Supply Line Material

The visible material used for the supply lines is copper.

6.2) Supply Line Conditions

Inspected and no Major deficiencies were noted at the time of the inspection.

Drain - Waste Lines

Drain Line Material

The visible portions of the waste lines are plastic.

6.3) Drain Line Conditions

Water Heater(s)

Water Heater Type Natural Gas.

Water Heater Location Basement.

Water Heater Capacity 75 Gallon.

6.4) Water Heater Conditions

- The Bradford White water heater was installed or manufactured in the **year 1998 or 1999.**Tested and in working condition on the inspection day.
- Inspected and no Major deficiencies were noted at the time of the inspection. Based on the
 manufacturer's suggested service life, the life expectancy of a water heater is about eight to
 12 to 15 years. That varies with the unit's location and design, installation quality,
 maintenance schedule, and water quality.



Water Heater Year 1998



Data plate.

7 Interiors

Walls - Ceilings - Floors

7.1) Wall Conditions











7.2) Ceiling Conditions

Inspected.

7.3) Floor Conditions

Inspected.

7.4) Heat Source Conditions

Inspected.

Windows - Doors

7.5) Interior Window Conditions

Check the exterior window section.

7.6) Interior Door Conditions

Inspected.

Electrical Conditions

7.7) Electrical Conditions

Inspected.

7.8) Lighting Conditions

7.9) Ceiling Fan Conditions

N/A

7.10) Smoke Detector Conditions



• A smoke detector was missing or removed at the lower level. Recommend smoke detectors on each level and near or in each bedroom. The client should contact the local Fire Marshall's office for proper locations.



Missing smoke alarm.

Fireplace

Fireplace Location

A fireplace is located in the family room.

Fireplace materials

The fireplace is metal/pre-fabricated.

7.11) Fireplace Conditions



- Inspected and no Major deficiencies were noted at the time of the inspection.
- Recommend chimney flue cleaning by a chimney sweep specialist. Creosote can accumulate and become a fire hazard if the fireplace and flue are not cleaned regularly.



Wooden fire chimney.



Fire box ok.



Flue ok .



Stairs.

7.12) Stairs location.

Front entrance.



Stairs ok.

7.13) Stairs Conditions

8 Kitchen

Walls - Ceilings - Floors

8.1) Wall Conditions

Inspected.



8.2) Ceiling Conditions

Inspected.

8.3) Floor Conditions

Inspected.

8.4) Heat Source Conditions

Inspected.

Windows - Doors

8.5) Kitchen Window Conditions

Inspected.

- 8.6) Kitchen Door Conditions
 - N/A, Not present. Not present or was not visible at the time of the inspection.

Electrical Conditions

8.7) Electrical Conditions

Inspected.

8.8) Lighting Conditions

Inspected.

Kitchen Sink - Counter tops - Cabinets

8.9) Counter Conditions

Inspected.

8.10) Cabinet Conditions

Inspected.

8.11) Sink Plumbing Conditions

• Inspected.



Sink faucet ok,



Under sink ok.

8.12) Garbage Disposal Condition

• N/A, Not present. Not present or was not visible at the time of the inspection.

Appliances

Stove - Range Type

The range is gas.

8.13) Stove - Range Condition

• Inspected and no Major deficiencies were noted at the time of the inspection.



Flame pattern observed ok,.



Oven ok.

8.14) Hood Fan Conditions

Inspected.

8.15) Dishwasher Conditions



• The dishwasher was not inspected due to personal items inside. Home inspectors are not allowed to remove personal items from any appliance or closet. It is recommended to check again on your final walkthrough or ask the seller before closing.



Dishwasher.



Personal items.

8.16) Fridge or freezer condition.



Fridge ok.

9 Bath All.

Walls - Ceilings - Floors

9.1) Wall Conditions











9.2) Ceiling Conditions

Inspected.

9.3) Floor Conditions

• Inspected.

9.4) Heat Source Conditions

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected


	Inspected.	
Windows - Doors		
9.5) Bathroom Window Conditions		
	Inspected.	
9.6) Bathroom Door Conditions		
	Inspected.	
Electrical Conditions		
9.7) Electrical Conditions		
	Inspected.	
9.8) Lighting Conditions		
	Inspected.	
9.9) Vent Fan Conditions		
	Inspected.	
Bathroom Sink		
9.10) Counter - Cabinet Conditions		
	Inspected.	
9.11) Sink Conditions		
Shower - Tub - Toilet		
9.12) Shower - Tub Conditions		
	Inspected.	
9.13) Toilet Conditions		
	Inspected.	

10 Basement


Walls - Ceilings - Floors

10.1) Basement Stair Conditions





Stairs ok.



Finish Basement

10.2) Wall Conditions

Inspected.

10.3) Ceiling Conditions

• Inspected and no Major deficiencies were noted at the time of the inspection.

10.4) Floor Conditions

Inspected.

10.5) Heat Source Conditions

Inspected.

Windows - Doors

10.6) Basement Window Conditions

Inspected.

10.7) Basement Door Conditions

Inspected.

Electrical Conditions

10.8) Electrical Conditions

Inspected.

10.9) Lighting Conditions

Inspected.

10.10) Sump Pump Conditions



• A sump pit was present. No sump pump was present and no water was observed at the time of inspection. This is not however an indication of future conditions. Whenever a sump pit is present, installation of a sump pump should be considered especially if water becomes present in the pit. Periodic inspection is recommended after a rainstorm.



Sump pit no water.

Other Conditions

10.11) Other Conditions

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected

N/A

11 Garage - Laundry

Walls - Ceilings - Floors

Garage Type

The garage is attached to the house.



Garage.

11.1) Siding Conditions (if detached)

Inspected.

11.2) Roof Conditions (if detached)

Inspected.

11.3) Wall Conditions

Inspected.

11.4) Ceiling Conditions

Inspected.

11.5) Floor Conditions

Inspected.

11.6) Window Conditions

Inspected.

11.7) Door Conditions

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected

Inspected.

11.8) Vehicle Door Conditions

R

• Both Garage door automatic openers were not operational or disconnected at the time of the inspection. Repair, replacement, and/or adjustments are needed.



Bad Push button.



Garage .





Disconnect connection

11.9) Electrical Conditions

11.10) Lighting Conditions

Inspected.

Laundry Room

Location

The laundry facilities are located in the laundry room.

11.11) Laundry Room Conditions

Inspected.

11.12) Washer condition

• Tested and in working condition on the day of inspection.



Dishwasher ok

11.13) Dryer Condition.

• Tested and in working condition on the day of inspection.

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected



Dryer ok.



Temp tested.

AS = Appears Serviceable | R = Repair | S = Safety | NI = Not Inspected

12 Foundation - Crawl Space

Found	lation
-------	--------

Foundation Type Basement.

Foundation Material Block.

12.1) Foundation Conditions

Inspected.

Flooring Structure

Flooring Support Type The wood framing floor system was constructed of 2 X 12

floor joists.

12.2) Flooring Support Conditions

Inspected.

Sewer Septic inspection

Type of Sewer Septic Sewer not inspected.

12.3) Sewer inspection

Recommendations.



- 1. Zee home inspection highly encourages all home buyers to conduct a sewer inspection whether they are buying a new home or older.
- 2. Q&A
- 3. Should I Get A Sewer Scope Inspection? Absolutely. As mentioned above, a sewer line is often one of the most costly things to repair in a home. Getting a sewer scope inspection can help you avoid investing in a home that has severe issues with the sewer/septic system.
- 4. If you want to ensure the lifespan of your sewer line, then inspections are the key. Regular inspections and maintenance can help avoid an untimely sewer line replacement by keeping your sewer line in good repair and avoiding severe damage by catching minor issues before they become big ones.
- 5. Sewer scope inspection can reveal damage to the pipes, blockages, and other problems. It also can spot potential problem areas before they develop into serious issues or hazards. After the inspection, clients will receive a report with findings and recommendations.